

FORCES ACTING ON AN AIRPLANE IN A TURN

In turns, some of the vertical lift is 'vectored' out to the side, resulting in a loss of altitude unless back pressure is applied to the elevator

